



令和プライム&Dコーナー

85155	車歴 (自家用以外は記入)	排気量	型式	評価点
	2000cc	6AA-RT5		
初度登録年月	車名	駆動方式	グレード	2WD
R2/9月	CR-Vハイブリッド	5D	e:HEV	4WD
			EXスターピース	
				内装 補助評価
				B

車検	R7年 9/17月	シフト	AT	特選品	S (P) 純正 (V) F (S) R (V)
走行	31,080 Km	冷房	AAC	セールスポイント	
外色	パール	色番	NH383P	★純正インターナショナル★フルセクTV!	
燃料	ガソリン・軽油・()	内装色		★Bカメラ★ブラウンレザーシート!	
輸入車		輸入区分	ディーラー・並行	★サンルーフ★パワーバックドア!	
		ハンドル	左・右	★パワーシート★ホンダセンシング!	
リサイクル	711160円	車検定員	5人		
登録No	福岡 303	7666			
車台No	RT5-1200185				
シリアルNo					


○注意事項 (修復・不具合箇所および状態等)

★LEDヘッド★アースキ-x2
★F-Rカメラ★
★ETC★

★ユーザー買取車★



○検査員報告 (USS使用欄)

ルーフ内カメラ、新タイヤ
カーナビ、シートベルト
小バグ、小凹



【荷台内寸】約 X X (cm)

長さ cm 幅 cm 高さ cm ← (車検証上の寸法)



一真正品に限り○をつけて下さい。
一車台番号は左詰めで車検証記載の通りへ記入下さい。

スベア



TRUE REPORT

RT5-1200185

Auction	USS KYUSHU
Chassis ID	RT5-1200185
Brand	HONDA
Model	CR-V HYBRID
Mileage	31,080 KM
Engine CC	2000
Year	2020
Grade	EX MASTERPIECE
Equipment	
Transmission	AT
Color	PEARL
Condition	4.5
Status	Sold
Auction date	2025-06-21
Sold Price	
Lot Number	85155
Powered by	japanauctionsheetsheetbd.org

Auction list explanation

A1 Small Scratch	X Need to be replaced
A2 Scratch	XX Replaced
A3 Big Scratch	B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)
E1 Few Dimples	B2 Big Distortion on (radiator) core support or back panel
E2 Several Dimples	Y1 Small Hole or Crack
E3 Many Dimples	Y2 Hole or Crack
U1 Small Dent	Y3 Big Hole or Crack
U2 Dent	X1 Small Crack on Windshield (approximately 1cm)
U3 Big Dent	R Repaired Crack on Windshield
W1 Repair Mark/Wave (hardly detectable)	RX Repaired Crack on Windshield (needs to be replaced)
W2 Repair Mark/Wave	X Crack on Windshield (needs to be replaced)
W3 Obvious Repair Mark/Wave (needs to be repainted)	B Dent with scratch
S1 Rust	P Paint marked
S2 Heavy Rust	H Paint faded
C1 Corrosion	G Stone chip in glass
C2 Heavy Corrosion	