



TRUE REPORT

ZVG11-1009649

Auction	USS TOKYO
Chassis ID	ZVG11-1009649
Brand	TOYOTA
Model	COROLLA CROSS
Mileage	11,730 km
Engine CC	1800
Year	2021
Grade	Z LEATHER
Equipment	AAC
Transmission	AT
Color	GREY
Condition	4.5
Status	SOLD
Auction date	2025-09-11
Finish price	
Lot Number	27592
Powered by	japanauctionsheetsheetbd.pro

Auction list explanation

A1 Small Scratch	X Need to be replaced
A2 Scratch	XX Replaced
A3 Big Scratch	B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)
E1 Few Dimples	B2 Big Distortion on (radiator) core support or back panel
E2 Several Dimples	Y1 Small Hole or Crack
E3 Many Dimples	Y2 Hole or Crack
U1 Small Dent	Y3 Big Hole or Crack
U2 Dent	X1 Small Crack on Windshield (approximately 1cm)
U3 Big Dent	R Repaired Crack on Windshield
W1 Repair Mark/Wave (hardly detectable)	RX Repaired Crack on Windshield (needs to be replaced)
W2 Repair Mark/Wave	X Crack on Windshield (needs to be replaced)
W3 Obvious Repair Mark/Wave (needs to be repainted)	B Dent with scratch
S1 Rust	P Paint marked
S2 Heavy Rust	H Paint faded
C1 Corrosion	G Stone chip in glass
C2 Heavy Corrosion	



プライムHVEVコーナー


No. 27592	車歴 (自家用以外は記入)	排気量 1800	型式 6AA-ZVG11	評価点 4.5
	初度登録年月 3/12月	車名 70-ラ70ス	グレード 5D 117V4" Z	

車検 8年12月	シフト FAT	純正品 S A	純AWD A V	PS A P	EW A P B
走行 11,730 Km	冷房 AAC	セールスポイント 117V4" マル-7 9インチディスプレイ トヨタセーフティセンス ETC・AC100V1500W 11-7レザーシート			
外色 元色 色替 70-70	カラーNo. 1H5	新車整備手帳 (保証書付) (有) 無			
燃料 ガソリン・軽油・()	内装色 70	名義変更期限 月 日			
輸入車用	輸入区分 ディーラー・並行	ハンドル 左・右			

リサイクル 預託金 9,730円	車庫定員 5人	積載量	登録No. K五 330 7 9207
○注意事項 (修復・不具合箇所および状態等) 保・取・スパーキー有			車台No. ZVG11-1009649
			シリアルNo.

○検査員報告 (USS使用欄)

117V4"内重の毛
小羽小羽



【荷台内寸】約	X	X	(cm)
長さ 449cm	幅 182cm	高さ 162cm	← (車検証上の寸法)

