



TRUE REPORT

ZVG11-1007816

Auction	USS YOKOHAMA
Chassis ID	ZVG11-1007816
Brand	TOYOTA
Model	Corolla Cross HYBRID
Mileage	46,735 km
Engine CC	1800
Year	2021
Grade	Z leather
Equipment	AAC
Transmission	AT
Color	BLACK
Condition	4.5
Status	SOLD
Auction date	2025-09-30
Finish price	
Lot Number	30763
Powered by	www.japanauctionsheetsbd.pro

Auction list explanation

A1 Small Scratch	X Need to be replaced
A2 Scratch	XX Replaced
A3 Big Scratch	B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)
E1 Few Dimples	B2 Big Distortion on (radiator) core support or back panel
E2 Several Dimples	Y1 Small Hole or Crack
E3 Many Dimples	Y2 Hole or Crack
U1 Small Dent	Y3 Big Hole or Crack
U2 Dent	X1 Small Crack on Windshield (approximately 1cm)
U3 Big Dent	R Repaired Crack on Windshield
W1 Repair Mark/Wave (hardly detectable)	RX Repaired Crack on Windshield (needs to be replaced)
W2 Repair Mark/Wave	X Crack on Windshield (needs to be replaced)
W3 Obvious Repair Mark/Wave (needs to be repainted)	B Dent with scratch
S1 Rust	P Paint marked
S2 Heavy Rust	H Paint faded
C1 Corrosion	G Stone chip in glass
C2 Heavy Corrosion	




プレミアム国産車コーナー

No. 30763	車歴 (自家用以外は記入)	排気量 1800	型 式 6AA-ZVG11	評価点 4.5
	初度登録年月 R 4 / 2 月	車 名 トヨタ カローラクロス	形式・ドア 5D	
車検 R 9 年 2 月 9 日		シフト FAT	純正品	SR カワ
走行 46,735 km		冷 房 AAC	純AV	PS ナビ
外 色 クロ	色 番 →	カ ラ ー 記 218	セーリングポイント パノラミックビューモニター セーフティセンス パワーバックドア ディスプレイオーディオ	
燃料 ガソリン	内 装 色		新車整備手帳 (保証書付) (有)	
輸入車用	年 式	輸入 区 分	ハ ン ド ル	譲渡書類有効期限 月 日
リサイクル 預託金 9,730 円	乗車定員 5 人	積載量	登 録 No. 湘南 330 た 8789	車 台 No. ZVG11-1007816
○注意事項 (修復・不具合箇所および状態等)			シリアル No.	

○検査員報告

シートシワ
トリム小キズ
ドアミラーキズ



【荷台内寸】約 × × (cm)
長さ 449 cm 幅 182 cm 高さ 162 cm

